



April 4004 aerial photograph obtained from Montana NRIS (http://nris.mt.gov/nsdi/orthophotos/2004_helena.asp)







April 2004 aerial photograph obtained from Montana NRIS (http://nris.mt.gov/nsdi/orthophotos/2004_helena.asp)







April 2004 aerial photograph obtained from Montana NRIS (http://nris.mt.gov/nsdi/orthophotos/2004_helena.asp)










April 2004 aerial photograph obtained from Montana NRIS (http://nris.mt.gov/nsdi/orthophotos/2004_helena.asp)







Hydrometrics, Inc.









Phase II RCRA Facility Investigation Site Characterization Work Plan East Helena Facility

PROPOSED PHASE II RFI SOIL BORINGS

FIGURE

3-1-2